## LASER INTERFEROMETER GRAVITATIONAL WAVE OBSERVATORY - LIGO -

CALIFORNIA INSTITUTE OF TECHNOLOGY MASSACHUSETTS INSTITUTE OF TECHNOLOGY

LIGO-T960117-00 -D 10/13/96 **Document Type** 

# **Drop Test - COC Carrier and Shipping Case**

**Craig Conley** 

Distribution of this draft: D. Coyne, S. Eliason, A. Lazzarini

This is an internal working note of the LIGO Project..

**California Institute of Technology** LIGO Project - MS 51-33 Pasadena CA 91125

Phone (818) 395-2129 Fax (818) 304-9834 E-mail: info@ligo.caltech.edu Massachusetts Institute of Technology LIGO Project - MS 20B-145 Cambridge, MA 01239

> Phone (617) 253-4824 Fax (617) 253-7014

E-mail: info@ligo.mit.edu

WWW: http://www.ligo.caltech.edu/

#### 1 ABSTRACT

٤

The drop test of the shipping case containing the COC carrier and dummy optic was performed at National Technical Systems in Fullerton, CA on 8/30/96. The dummy optic, secured within the COC carrier, was made of aluminum, and exactly the size and shape of a large LIGO optic, but with 27% more mass.

The case was dropped in ten different orientations from a height of 36" onto a concrete floor. The setup consisted of a hinged platform with a stretched bunji cord attached for quick separation from the case at drop-time, a mounted triaxial accelerometer (accel), and electronic monitoring equipment including two oscilloscopes.

The test revealed inadequacy of the shipping case, with the current foam insert design, to shield the carrier from the resulting shock forces. The carrier experienced shock forces of up to approximately 200g. It appears likely that a greater thickness of foam (as well as a larger case) will be deemed necessary. Stress analysis of the COC carrier standoffs will determine whether the standoffs should be thickened and provided with threaded inserts.

#### 2 PROCEDURE RECAP

(See attached NTS Log Sheet, graphs, sketches and photos)

The accel was initially mounted with dental cement to the side of the dummy optic, approximately centered between it's top and bottom, with axes oriented as sketched. After a couple of drops to get the 'feel' and adjust equipment settings, the setup was seen to provide very good control of the drop orientation with no interference from the platform owing to the pre-loaded bunji cord. The drops were executed with good results until the 7th drop, at which time the case and carrier were opened revealing damage to the carrier including completely stripped threads in the mounting screw holes of the hinged standoff, looseness of the other two standoffs at the base, bending of the top plate hold-down screws and locating pins, fracturing of the L-section tefflon base pad at the hinged standoff, buckling of the top face of the cover and a sheared mounting screw to the left handle plate. The accel was broken free from the optic and had left an imprint in the side of the cover. After re-mounting the accel to the cover as sketched with the original axes orientations, the test was resumed with the optic in its non-secure condition in the damaged carrier. The accel was broken loose again on the 8th drop, and re-mounted in approximately the same location for the 9th and 10th drops. The final three drops yielded questionable output results (see table below). Through the course of the test, the case incurred mainly cosmetic damage, and was not rendered unusable.

NOTE: The worst case drop (with this test's carrier/case orientation) would presumably be a front side drop, in which the weaker mounted hinged standoff would take the full impact of the optic. This drop was not executed in this test

## APPENDIX 1 PEAK ACCELERATION VALUES

Table 1:

Drop #	Orientation	Peak Acceleration (G)		
		X <sub>p</sub>	Yp	$\mathbf{Z}_{\mathbf{p}}$
1	bottom	-72	-2	-2
2	side, hinge	-78/97	193/-80	106/-115
3	left side, handle	-49/15	-15/8	-75/0
4	bottom left edge	80/-70	197/168	67/-118
5	top left edge	-95/29	-67/67	-50/35
6	top side edge (hinge)	21/3	40/-3	4/-1
7	bottom side edge (latch)	-82/15	-71/49	-27/53
8 <sup>a</sup>	top left cor- ner (latch)	-110/80	-70/55	-112/128
9 <sup>a</sup>	bottom left corner (latch)	-175/74	197/-60	164/-119
10 <sup>b</sup>	top	14/-12	8/-9	6/-8


a. Suspect output traces. Plots decay to non-zero steady state values.


b. Outputs not as expected.  $Y_p \& Z_p$  values should be near zero.





# **GENERAL LOG SHEET**


I		ALL DROP MJO 673-3185	
J.		MA TASTITUTE OF TECH. DATE 8-30-96	
ı		P/N S/N	
SPECIFICATION	ON CUSTO	MER VERBAL PAR	<b>,</b>
DATE	TIME	LOG ENTRIES	INITIAL
9-30-96	0.900	SET UP DEDP APARATIS, ATTACH ACCELEROMETER  TO DUMMY MASS START TEST  DROP I BOTTOM COMPLETE  2 SIDE (HINGE), COMPLETE  3 CEPT SIDE (HANDLE) COMPLETE	
		4 BOTTOM CEFT EXCE COMPLETE	
		5 TOP LEFT EDGE, COMPLETE	
		6 TOP SIDE EIKE (HINGE), COMPLETE	
		7 BOTTOM SIDE EINE (LATCH), COTMPLETE	
		8 TOP LEFT CORNOR (LATE) COMPLETE	
		9 BOTTOM LEFT CORNER (LATCH) COMPLETÉ	
		10 TOP COMPLETE	.,
8-30-96	1330	TEST COMPLETE	
		ļ ———————	
		X ACCEL TO STORE	
		Ø: →z	
			<del></del>
			- · · · · · · · · · · · · · · · · · · ·
		TEST BY Thereber DATE 8-30-96	
PAGE	OF	ENGR. GOV'T QAR	












SQUARE

Buffalo, New York Printed in U.S.A.



Buttalo, New York Printed in U.S.A.


SQUARE





10ms/DIV

Test Report No. 673-3185











Buffalo, New York - Printed in U.S.A.


5ms/biv




Test Report No. 673-318




Test Report No 9 w ú 185




Tes rt Report No. 9 ũ -3185 Bulfalo, New York Printed in U.S.A.










Buffalo, New York Printed in U.S.A.



Tes rt Report No σ 3185






10 ~3/010


Test Report No. 673-3185

Company of Company















Test

Report


No

673-318





Tes rt Report No. 673 -3185






#### EQUIPMENT LIST

Description	Apparatus	<u>Calibration</u>
SHOCK	Kikusui Digital Oscilloscope, Model 5020A, ± 3%, NTS Control No. D-4863-F	6 Months Due 12-6-96
	Kistler Digital Oscilloscope, Model 5020A, NTS Control No. MET-4225-F	6 Months Due 9-8-96
	Kistler Dual Mode Amplifier, Model 5004, NTS Control No. MET-4230-F	6 Months Due 1-15-97
	Kistler Dual Mode Amplifier, Model 5004, NTS Control No. MET-4232-F	6 Months Due 1-15-97
	Kistler Dual Mode Amplifier, Model 5004, NTS Control No. MET-4231-F	6 Months Due 1-2-97
	PCB Accelerometer (Tri-Axial), Model 356A07, NTS Control No. D-5006-F	6 Months Due 2-16-97
	Western Graphtec X-Y Plotter, Model WX1200E, NTS Control No. D-4807-F	6 Months Due 12-7-96


13-782 50) SHEFIS, FILLER 5 SOUNTE 22-281 500 SHEFIS SPIC-ARSP 5 SOUNTE 22-289 200 SHEFIS SPIC-ARSP 5 SOUNTE 23-289 200 PECYCLED WHITE 5 SOUNTE 23-382 200 PECYCLED WHITE 5 SOUNTE 24-28-385 200 PECYCLED WHITE 5 SOUNTE


Mailonal Brand



19.782 800 SHEETS, FILLER S SOUARE 18.08 1 80 SHEETS EFECTOR SEGUANE 18.08 SHEETS EFE SEGUANE 18.08 SHEETS EFE SEGUANE 18.08 100 RECYCLED WHITE 5 SQUANE 18.08 200 RECYCLED WHITE 5 SQUANE Hannus S.A.

Mational "Brand






Circulor outant has 2 /4" diametrial lay coround corrier top cover


from insert top

19-782 GOO SHEETS, FILLER S SOLUME 22-301 SON SHEETS FILES SEGURATE A2-302 200 SHEETS FILES SOLUME CS-302 200 SHEETS FILES SOLUME A2-302 200 SHEETS FILES SOLUME MARNING SA





Circular cutaut has </8" diametrical play around the base of the carrier cover but x 11/2" rodial play around the top of the corrier conter)


from Tusest bottom














Z

