



1. Flooding at access road bridge.

G960189-01 -O-P

2. Southeast arm at corner station.



G960189-02 -O-P



3. Southeast arm at station 10+00.

G960189-03 -O-P



4. Southeast arm at station 27+00.

G960189-04-O-P



5. Southeast arm at station 27+00 at culvert crossing.

G960189-05-O-P



6. Southeast arm at culvert 27+00.

G960189-06-O-P



7. Southeast arm at station 33+00 showing 24" line between trenches.

G960189- 07-O-p

8. Southeast arm at station 43+00.

G960189- 08-O-p



9. Southeast arm at station 43+00.

G960189- 09-O-p



10. Southeast arm at station 87+00.

G960189- 10 -O-P

11. Southeast arm at station 83+00.

G960189- 11 -O-P



12. Southeast arm (#2) at station 106+00.

G960189- 12 -O-P



13. Southeast arm (#2) at station 90+00.

G960189- 13 -O-P



14. Southeast arm (#2) at station 90+00.

G960189- 14 -O-P



15. Southeast arm (#2) at station 106+00 inlet.

G960189- 15 -O-P



16. Southeast arm (#2) at station 110+00 erosion to be repaired.

G960189-16 -O-P

17. Southeast arm (#2) at station 91+00.

G960189-17 -O-P



18. East side of construction complex.

G960189-18 -O-P



19. Graders receiving laser monitoring equipment for fine grading.

G960189-19 -O-P



20. Dozers parked, waiting for soil to dry enough to start the drying and compaction process.

G960189-20 -O-P



21. Dump trucks standing by.

G960189-21 -O-P



22. Northwest quadrant at center section showing the results of back dragging to remove puddles.

G960189-22-O-P

23. Same as previous photo #22.

G960189-23-O-P



24. Corner station at NE quadrant showing puddling on rolled area.

G960189-24-O-P