Document #: C1000770-v1

Drawing List for SOW C1000769:

DCC#	rev	Description		Total Quantity needed:	Delivered to MIT by 8/27/2010	Delivered to LHO by 9/22/2010	Delivered to LLO by 10/27/2010
D0902488	v2	bracket	stage 0-1 spring pre-loader (pusher)	12	3	6	3
D0902483	v2	saddle	stage 0-1 spring pre-loader (pusher)	12	3	6	3
D0902200	v1	top saddle	stage 0-1 spring pre-loader (pusher)	24	6	12	6
D0902594	v2	threaded pivot	stage 0-1 spring pre-loader (pusher)	24	6	12	6
D0902599	v2	step 1 bolt	stage 0-1 spring pre-loader (pusher)	24	6	12	6
D0902602	v1	bottom pivot	stage 0-1 spring pre-loader (pusher)	24	6	12	6
D0902603	v1	bolt cap	stage 0-1 spring pre-loader (pusher)	24	6	12	6
D0902193	v1	puller bolt	stage 1-2 spring pre-loader (puller)	12	3	6	3
D0902188	v1	puller rod	stage 1-2 spring pre-loader (puller)	24	6	12	6
D0902189	v1	spacer	stage 1-2 spring pre-loader (puller)	12	3	6	3
D0902190	v1	puller pivot	stage 1-2 spring pre-loader (puller)	12	3	6	3
D0902191	v1	puller saddle	stage 1-2 spring pre-loader (puller)	12	3	6	3
D0902187	v1	connection block	stage 1-2 spring pre-loader (puller)	12	3	6	3
D0902186	v1	centering washer	stage 1-2 spring pre-loader (puller)	12	3	6	3
D0902192	v1	end bracket	stage 1-2 spring pre-loader (puller)	12	3	6	3
D1000745	v1	receiver base	lifting hook	5	0	3	2
D1000746	v1	receiver vertical	lifting hook	10	0	6	4
D1000747	v1	pin	lifting hook	5	0	3	2
D1000748	v1	pin keeper	lifting hook	5	0	3	2
D1000753	v1	safety base	lifting hook	15	0	9	6
D050452	v2	alignment pin	stage 0-2 tooling post	45	3	30	12
D1001111	v1	alignment washer	stage 0-2 tooling post	45	3	30	12
D050453	v2	standoff pin	stage 1-2 tooling post	45	3	30	12
D1001113	v1	standoff washer	stage 1-2 tooling post	45	3	30	12
D0902672	v1	bottom cable tie	cable ties	90	6	60	24
D0902671	v1	top cable tie	cable ties	90	6	60	24
D0902673	v1	joint cable tie	cable ties	90	6	60	24