NOTES CONTINUED:

⑤ SCRIBE, ENGRAVE, OR MECHANICALLY STAMP (NO INKS OR DYES) DRAWING PART NUMBER AND REVISION ON NOTED SURFACE FOLLOWED ON THE NEXT LINE BY A THREE DIGIT SERIAL NUMBER. SERIAL NUMBERS START AT 001 FOR THE FIRST ARTICLE AND PROCEED CONSECUTIVELY. USE .07" HIGH CHARACTERS.
EXAMPLE: DXXXXXXX-VY, S/N 001.
A VIBRATORY TOOL MAY BE USED.

⑥ MACHINE ALL SURFACES.

REV.	DATE	DCN #	DRAWING TREE #









NOTES AND TOLERANCES: (UNLESS OTHERWISE SPECIFIED)									
DIMENSIONS ARE IN MILLIMETERS TOLERANCES: .XX ± 0.10 .XXX ± 0.010 ANGULAR ± 0.2°	1. INTERPRET DRAWING PER ASME Y14.5-1994. 2. REMOVE ALL SHARP EDGES, R.02 MIN. 3. DO NOT SCALE FROM DRAWING. 4. ALL MACHINING FLUIDS MUST BE FULLY SYNTHETIC, FULLY WATER SOLUBLE AND FREE OF SULFUR, SILICONE, AND CHLORINE.		LIGO CALIFORNIA INSTITUTE OF TECHNOLOGY MASSACHUSETTS INSTITUTE OF TECHNOLOGY		PART NAME: FIBRE BOW LINEAR STAGE INTERFACE				
	MATERIAL: 6061-T6 Al	FINISH: 1.6 µm	SYSTEM: ADVANCED LIGO	SUB-SYSTEM: SUS	DESIGNER: L.CUNNINGHAM		SIZE: c	DWG. NO.: D1002212	REV.: v3
			NEXT ASSY		DRAFTER: L Cunningham				
					CHECKER				
					APPROVAL		SCALE: 2:1	PROJECTION:	SHEET 1 OF 1