





- H1 #4 screw, 3/8"
- H2 #4 screw, 3/8"
- McMaster-Carr 90272A108
- H3 #4 lock washer
- H4 #4 lock washer
- McMaster-Carr 91113A005
- H5 #4 nut
- H6 #4 nut
- McMaster-Carr 90480A005

- H7 #4 screw, 3/8"
- H8 #4 screw, 3/8"
- McMaster-Carr 91099A165
- H9 #4 lock washer
- H10 #4 lock washer
- H11 #4 nut
- H12 #4 nut

- H13 #4 screw, 3/8"
- H14 #4 screw, 3/8"
- McMaster-Carr 90272A108
- H15 #4 lock washer
- H16 #4 lock washer
- McMaster-Carr 91113A005
- H17 #4 nut
- H18 #4 nut
- McMaster-Carr 90480A005

- H19 #4 screw, 3/8"
- H20 #4 screw, 3/8"
- McMaster-Carr 91099A165
- H21 #4 lock washer
- H22 #4 lock washer
- H23 #4 nut
- H24 #4 nut



Title		
Power Distribution Board		
Size	Number	Revision
A	D1000815	1
Date:	4/6/2010	Sheet 1 of 1
File:	C:\Users\...\PowerDist1.SchDoc	Drawn By: Daniel Sigg