


DCN No.	E010092-00-D		
SHEET	1	OF	1
5/10/01			


DOCUMENT CHANGE NOTICE (DCN)

DOCOME	INT CHANGE NOTICE (DCN)			
DOCUMENT No. (DOC-REV-GP. ID)	TITLE	<u> </u>	NEW REV.	
LIGO-E010091-00-D	Chamber Component Configuration HAM1 MAR/APR 2001 Continued			
CHANGE DESCRIPTION (FROM/	Official Release. Rev. change from 00 to	A.		


			··· ·	
THE RESIDENCE OF THE STATE OF T		1.14. M. V. P. M. W. P. M. V. P. M. W. P. M. V. P. M. W. P. M. V. P. M. W.		
		distributive contraction of the		
(A)				
REASON FOR CHANGE: Upda	ted for 4k Detector Installation			
		100 CH (100 CH	199,	
ACTION: Incorporate chang	e Attach DCN to drawing(s) Other action (specify):			
DISPOSITION	OF HARDWARE (IDENTIFY SERIAL NUMBERS)	DCN DISTRIBUTION (X=in	icl. docs)	
No hardware affected (reco			Coles	
List S/Ns which comply alre	■ 11 (3) (2) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	Sanders Shoemaker Tyler Weiss		
List S/Ns to be reworked or	H1. 20. 194 (A.M.) 4			
List S/Ns to be built with th				
List S/Ns to be retested per	X Reitze X Tanner			
SAFETY, COST, SCHEDULE, REC	QUIREMENTS IMPACT? No Yes (If yes, enter Change	Request number)	
APPROVALS	+	OVALS (specify)	DATE	
ORIGINATOR: B. Weaver	13. We gray 18 bord 10 [27 0]			
TASK LEADER: S. Whiteon		POLICE AND A STATE OF THE STATE		
DCC RELEASE: Whitcon				
DUC HELEASE: WILLA	n 11.11.01			




HAM1 Faraday Isolator and MMT1 viewed from above. North is to the left, South is to the right.




HAM1 MMT1 (foreground) and MMT3 (background). Looking South.




HAM1 MMT1 (foreground), SM1 (left background) and MC3 (right background). Looking North.



HAM1 MMT3 front, looking South.



HAM1 MMT3 and Sensor/Actuator connections, viewed from the West door, looking Southeast.



HAM1 MC1 closeup view from above.



HAM1 SM1 viewed from above. North is to the left.