ااااالا
LIGO

_ ~		
IN'N	Na	E020738-00-0
	TAO.	LU40/30-00-0

California Institute of Technology			DCN No. E020738-00-C						
Document Ch	usetts Institute of Tec lange Notice		Sheet 1	of 1					
DOCUMENT No. (DOC-REV-GP.ID)		TITLE							
D010038-B	LHO 4K SOS Contro		С						
D010036-03	LHO 4K SUS Rack A	04							
Moved MC2 output controls to a separate crate to accommodate common mode input from LSC.									
REASON FOR CHANGE:Accommodate MC 2 length path from LSC common mode loop.									
ACTION:									
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS) DCN DISTRIBUTION									
No hardware was affect	cted (record change only):	:	Barish	Coles	Coyne Sanders				
List S/Ns which comply already: List S/Ns which comply already: Lazzarini Shoemaker Stapfer									
List S/Ns to be reworked/scrapped: Weiss Whitcomb									
List S/N's to be built with this change:									
☐ List S/Ns to be retested per this change:									
System being modified per drawings.									
SAFETY, COST, SCHEDULE,	REQUIREMENTS IMPAC	T? NO YES (I	f YES, enter CR (CC	CB) or TCP (TR	B) #)				
APPROVALS	S: DATE	OTHER APPROVALS (SPECIFY)		DATE					
ORIGINATOR:	7/19/02								
TASK LEADER:									
GROUP LEADER:									
DCC RELEASE:									