

DCN No.	E	98002	21-00-E
SHEET	1	OF	2

DOCUMEN	NT CHANGE NOTI	CE (DCN)			
DOCUMENT No. (DOC-REV-GP. ID)		TITLE		NEW REV.	
D950140-A-E	Orientation of the Beam Tube En	closure Foundation with Res	pect to the Local Horizontal	В	
D950148-0-E LVEA and VEA Foundations Relative to the Beam Line					
The state of the s	and the second s	Hilly deliver the contract of			
CHANGE DESCRIPTION (FROM/TO):			<u></u>	
D950140-A-E: 1. Change	d Louisiana Beam Tube def	initions:			
	FROM	ТО			
	Southeast (X) Arm	Southeast (Y) Arm			
THE COLUMN TO	Southwest (Y) Arm	Southwest (X) Arm			
REASON FOR CHANGE: Drawin	ALL AND	Other action (specify):			
		BURN FOR MANAGEMENT			
	F HARDWARE (IDENTIFY SERIAL N	UMBERS)	DCN DISTRIBUTION (X≔Incl.		
No hardware affected (record			Althouse Barish XCol Coyne XLazzarini Lin	es dquist	
List S/Ns which comply alread			Raab Sanders Sho	emaker	
List S/Ns to be reworked or so			XStapfer X Tyler We Whitcomb Zydowicz		
List S/Ns to be built with this			X F Asiri X L Jo		
	is change.			нсэ	
		· · · · · · · · · · · · · · · · · · ·	X A. Sibley	SBNDND 1 3	
			11 Peruta transport (1998) 1991		
CAFETY COST SCHEDIILE DECIL	DEMENTS IMPACT2 III No. [Vec /if yes enter Change B	leguest number		
SAFETY, COST, SCHEDULE, REQU		Yes (If yes, enter Change R)	
APPROVALS:	DATE	OTHER APPROV	ALS (specify) DAT		
APPROVALS: ORIGINATOR: W. Baldwin-		OTHER APPROV. BT TASK LEADER: L.	Jones 3/3//5		
APPROVALS:	DATE 3/27/98	OTHER APPROV. BT TASK LEADER: L CC TASK LEADER: F. A	ALS (specify) DAT		

DCN No. E980021-00-E SHEET 2 OF 2

DOCUMENT CHANGE NOTICE

CHANGE DESCRIPTION (FROM/TO):

D950148-0-E, sheet 2, Changed Louisiana Beam Tube definitions:

	FROM	ТО
 View B-B	Southeast,Y Arm	Southwest, X Arm
 View A-A	Southwest, X Arm	Southeast, Y Arm

This is a labeling change to correct a drawing error.

D950148-0-E, Table on Sheet 3, Changed Louisiana Beam Tube definitions:

FROM;

LIVINGSTON X END 30.9 (784) 0'1.8" (.0	rad)
Y END 30.8 (781) 1'4.7" (0.	

TO:

 SITE	ARM	STATION		 D in (mm)
 LIVINGSTON	X	END END	30.8 (781) 30.9 (784)	1'4.7" (0.314) 0'1.8" (.009)

This change reorders the table to correct a drawing error.



DCN	No.	E980021-00-E					
SHE	T	1	0F	2			

DOCUM	ENT CHANGE	NOTIC	E (DCN)		
DOCUMENT No. (DOC-REV-GP. ID)			TITLE		NEW REV.
D950140-A-E	Orientation of the Beam	Tube Enclos	sure Foundation with Res	spect to the Local Horizontal	В
D950148-0-E	LVEA and VEA Founda	tions Relativ	e to the Beam Line		A
CHANGE DESCRIPTION (FROM	//TO):				
D950140-A-E: 1. Char	nged Louisiana Beam T	ube defini	tions:		
er en	FROM		ТО		- 19 g
	Southeast (X) A	Arm S	outheast (Y) Arm		
	Southwest (Y)	Arm S	outhwest (X) Arm		
REASON FOR CHANGE: Drav		wing(s)	Other action (specify):		
DISPOSITION	OF HARDWARE (IDENTIFY S	SERIAL NUMI	BERS)	DCN DISTRIBUTION (X=incl.	docs)
No hardware affected (rec				Althouse Barish XCole	
List S/Ns which comply all	ready:			Coyne XLazzarini Lind	
List S/Ns to be reworked o	or scrapped:			XStapfer X Tyler Wels	-
List S/Ns to be built with the	his change:			Whitcomb Zydowicz	
List S/Ns to be retested pe	er this change:			X F. Asiri X L. Jot	nes
				X A. Sibley	
					:
SAFETY, COST, SCHEDULE, RE	QUIREMENTS IMPACT?	I No ☐ Y	es (If yes, enter Change R	equest number)
APPROVAL	s:	DATE	OTHER APPROVA	ALS (specify) DAT	E
originator: W. Baldwi	$r = \sqrt{2}$	/27/98	BT TASK LEADER: L. J	ones 3/31/98	f
TASK LEADER:		_ }	CC TASK LEADER: F. A		
GROUP LEADER: A. Lazzari		-3-98]		
DCC RELEASE:	11 3/	31/8			

OCN No. E980021-00-E SHEET 2 OF 2

DOCUMENT CHANGE NOTICE

CHANGE DESCRIPTION (FROM/TO):

D950148-0-E, sheet 2, Changed Louisiana Beam Tube definitions:

	FROM	ТО
View B-B Southeast, Y Arm		Southwest, X Arm
View A-A	Southwest, X Arm	Southeast, Y Arm

This is a labeling change to correct a drawing error.

D950148-0-E, Table on Sheet 3, Changed Louisiana Beam Tube definitions:

FROM:

SITE	ARM	STATION	B in (mm)	C in (mm)	min-sec (mrad)	
 LIVINGSTON	X Y	END END	30.9 (784) 30.8 (781)		0'1.8" (.009) 1'4.7" (0.314)	

TO:

SITE	ARM	STATION	B in (mm)	C in (mm)	D in (mm)
LIVINGSTON	X Y	END END	30.8 (781) 30.9 (784)		1'4.7" (0.314) 0'1.8" (.009)

This change reorders the table to correct a drawing error.