			DCN No. E980086	5-00-D
	CALIFORNIA INSTITUTE OF TEC MASSACHUSETTS INSTITUTE OF 1		SHEET 1 OF 1	1
	ENT CHANGE NOTI			
DOCUMENT No. (DOC-REV-GP. ID)		TITLE		NEW REV.
E980082-A-D	LOS Alignment Fixture Fat	prication Specification		В
			· · · · · · · · · · · · · · · · · · ·	
			1818 101979 107 91 9 Joseph Jo	
CHANGE DESCRIPTION (FROM/	·			
	mponents: Support Beam D9		02 and Lift Truck D98	30003.
	prasive Cloth/Paper requirements (and document) from Align		on Fixtures	
······································				
	19 / 20 / 20 / 20 / 20 / 20 / 20 / 20 / 2			
	······································			
			1. A. M. M. M. Margana and M. Margana.	
	ан андан андан Андан андан анд			
				····
REASON FOR CHANGE: 1. Ot	her components to be procure	d at the same time. 2. The	ese componets are not ents lifted 3 Avoid co	t perma-
nently installed in the vacu	uum and therefore can have st	rick cleanliness requirem	ese componets are not ents lifted.3.Avoid co	t perma- onfusion.
REASON FOR CHANGE: 1. Of nently installed in the vacu ACTION: X Incorporate chang	uum and therefore can have st	d at the same time. 2. The rick cleanliness requirem Other action (specify):	ese componets are not ents lifted.3.Avoid co	t perma- onfusion.
ACTION: X Incorporate chang	uum and therefore can have st	rick cleanliness requirem Other action (specify):	ese componets are not ents lifted.3.Avoid co DCN DISTRIBUTION (X=ir	nfusion.
ACTION: X Incorporate chang	uum and therefore can have st ge Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N	rick cleanliness requirem Other action (specify):	ents lifted.3.Avoid co	nfusion.
nently installed in the vacu ACTION: Incorporate chang DISPOSITION	Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N rd change only)	rick cleanliness requirem Other action (specify):	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini	nfusion. ncl. docs) Coles Lindquist
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: Comparison of the state of the	Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady:	rick cleanliness requirem Other action (specify):	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler	onfusion. ncl. docs) Coles
nently installed in the vacu ACTION: Incorporate change DISPOSITION X No hardware affected (reco List S/Ns which comply alreed	aum and therefore can have st Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady: scrapped:	rick cleanliness requirem Other action (specify):	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders	nfusion. ncl. docs) Coles Lindquist Shoemaker
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: State of the stat	Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady: scrapped: is change:	rick cleanliness requirem Other action (specify):	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zuch	onfusion. ncl. docs) Coles Lindquist Shoemaker Weiss ker
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: Second content of the second content of th	Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady: scrapped: is change:	rick cleanliness requirem Other action (specify):	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zucl X Barton X K. M	nct. docs) Coles Lindquist Shoemaker Weiss ker Jason
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: Second content of the second content of th	Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady: scrapped: is change:	rick cleanliness requirem Other action (specify):	ents lifted.3.Avoid co DCN DISTRIBUTION (X=ir Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zucl X Barton X K. M Camp Jone	nct. docs) Coles Lindquist Shoemaker Weiss ker Jason
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: Second content of the second content of th	Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady: scrapped: is change:	rick cleanliness requirem Other action (specify):	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zucl X Barton X K. M Camp Jone X Fine	nct. docs) Coles Lindquist Shoemaker Weiss ker Jason
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: Second stress of the second stress of t	Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL Nord change only) eady: scrapped: is change: this change:	rick cleanliness requirem	ents lifted.3.Avoid co DCN DISTRIBUTION (X=ir Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zuck X Barton X K. M Camp Jone X Fine X Hazel	nct. docs) Coles Lindquist Shoemaker Weiss ker Jason
nently installed in the vacu ACTION: Incorporate chang DISPOSITION DISPOSITION Image: Safety cost, schedule, record Image: Safety, cost, schedule, record	aum and therefore can have st ge Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL Nord change only) eady: 'scrapped: is change: 'this change: 'UIREMENTS IMPACT?	rick cleanliness requirema Other action (specify): IUMBERS) IUMBERS) IUMBERS	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zucl X Barton X K. M Camp Jone X Fine X Hazel quest number	onfusion. ncl. docs) Coles Lindquist Shoemaker Weiss ker Jason S
nently installed in the vacu ACTION: Incorporate change DISPOSITION Image: Solution of the second s	Attach DCN to drawing(s) Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady: scrapped: is change: this change: DUIREMENTS IMPACT? No DATE	rick cleanliness requirem	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zucl X Barton X K. M Camp Jone X Fine X Hazel quest number	nct. docs) Coles Lindquist Shoemaker Weiss ker Jason
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: Solution of the second se	aum and therefore can have st ge Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL Nord change only) eady: 'scrapped: is change: 'this change: 'UIREMENTS IMPACT?	rick cleanliness requirem	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zucl X Barton X K. M Camp Jone X Fine X Hazel quest number	onfusion. ncl. docs) Coles Lindquist Shoemaker Weiss ker Jason S
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: Solution of the second se	Attach DCN to drawing(s) Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady: scrapped: is change: this change: DUIREMENTS IMPACT? No DATE	rick cleanliness requirem	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zucl X Barton X K. M Camp Jone X Fine X Hazel quest number	onfusion. ncl. docs) Coles Lindquist Shoemaker Weiss ker Jason S
nently installed in the vacu ACTION: Incorporate chang DISPOSITION Image: Solution of the second se	Attach DCN to drawing(s) Attach DCN to drawing(s) OF HARDWARE (IDENTIFY SERIAL N ord change only) eady: scrapped: is change: this change: DUIREMENTS IMPACT? No DATE	rick cleanliness requirem	ents lifted.3.Avoid co DCN DISTRIBUTION (X=in Althouse Barish Coyne Lazzarini Raab Sanders Stapfer Tyler Whitcomb Zydowicz Bork Zucl X Barton X K. M Camp Jone X Fine X Hazel quest number	onfusion. ncl. docs) Coles Lindquist Shoemaker Weiss ker Jason S

ç4

CALIFORNIA INSTITUTE OF TECHNOLOGY MASSACHUSETTS INSTITUTE OF TECHNOLOGY COMPONENT SPECIFICATION						E980082-B- D DRWG NO. REV. GID SHEET 1 OF 3		
	OS INSTALL ABRICATIO							
APPROVALS:	DATE	REV	DCN NO	BY	СНК	DCC	DATE	
DRAWN: J. Hazel	4/14/98	A	E980081-00-D	n/a	n/a	n/a	n/a	
CHECKED:			E980086-00-D	JSH			4-27-98	
APPROVED:								
DCC RELEASE: HUML	5/1/98							
1 INTRODUCTIO	DN		·	-				

1.1. Objectives and Scope

The scope of this document is limited to the specifications for the fabrication of the LOS (Large Optics Suspension) installation fixtures, including the Alignment Fixture, Support Beam, Lift Table and Lift Truck.

1.2. Applicable Documents

LIGO-D980001: Alignment Fixture

LIGO-D980002: Lift Table

LIGO-D980003: Lift Truck

LIGO-D980182: Support Beam

LIGO-D960132: Large Optic Suspension Assembly, LOS1;Reference only - not required for fabrication LIGO-L970196: Part Numbers and Serialization of Detector Hardware

2 SPECIFICATION FOR FABRICATION

2.1. Physical Configuration

Build in accordance with:

LIGO-D980001: Alignment Fixture LIGO-D980002: Lift Table LIGO-D980003: Lift Truck LIGO-D980182: Support Beam

2.2. Fabrication

2.2.1. Cost Cutting

LIGO solicites the contractor to provide construction techniques and approaches for approval which would reduce the fabrication costs of the installation fixtures. Please contact the cognizant engineer concerning these issues. For example, some parts, shown as machined from one piece of material blank, may be welded or bolted together from more than one piece of material.



CALIFORNIA INSTITUTE OF TECHNOLOGY MASSACHUSETTS INSTITUTE OF TECHNOLOGY E980082-B-D

DRWG NO. REV. GID

COMPONENT SPECIFICATION

CONTINUATION SHEET

SHEET 2 OF 3

TITLE

LOS INSTALLATION FIXTURES FABRICATION SPECIFICATION 2.2.2. Protection from Contamination

A number of components of the installation fixtures are made of stainless steel (see drawing). No carbon steel hooks, fork lift forks, grapples or chains shall be allowed to contact the stainless steel.

Stored materials (raw materials or work-in-process) shall be protected from the shop atmosphere when not being handled (or worked on) by plastic sheets or similar protective covers. Polyethylene plastic sheet is acceptable. Raw materials shall be protected from contamination throughout the fabrication process. Smoking is not allowed in any LOS installation fixtures storage or manufacturing area.

2.2.3. Part Machining

Liquid contaminants/Machining Lubricants

Liquids containing hydrocarbons or other contaminants, other than the machining fluids specified herein, shall not be allowed to come into contact with installation fixtures material at any time. All machining fluids shall be water soluble and free of sulfur, chlorine and silicone; such as Cincinnati Milacron's Cimtech 410 (stainless steel) or Hangsterfer's S-500CF (all metals).

2.2.4. Welding

Welders must be certified to American Welding Society (AWS) or American Society of Mechanical Engineering (ASME) standards. An inert shield gas (e.g. Argon) must be used in all installation fixtures welding. All welding and fitting shall be done in clean manufacturing space.

2.2.5. Assembly

Clean all piece parts with isopropyl alcohol and acetone before assembly. In particular, clean all through, blind and threaded holes, especially ones that shall have dowel pins and Helicoil inserts installed. Assemble without lubrication. Verify proper fit. LIGO will verify proper performance and design.

2.3. Quality Assurance/Control

2.3.1. Identification

Separate (non-welded) parts and assemblies shall be marked with laser marking or acid etch techniques. A vibratory tool with a minimum tip radius of 0.0005" is acceptable for marking on surfaces which are not hidden from view. Engraving is also permitted.

Separate (non-welded) parts and assemblies to be serialized according to the document titled Part Numbers and Serialization of Detector Hardware, LIGO-L970196. This document allows for "bag-and-tag" type of identification for small parts.



CALIFORNIA INSTITUTE OF TECHNOLOGY MASSACHUSETTS INSTITUTE OF TECHNOLOGY E980082-B- D

DRWG NO. REV. GID

COMPONENT SPECIFICATION

CONTINUATION SHEET

SHEET 3 OF 3

LOS INSTALLATION FIXTURES FABRICATION SPECIFICATION

2.3.2. Serial Number

TITLE

The Serial number shall be of the format: Dxxxxxx-y S/N nnn Where

Dxxxxxy is the LIGO piece part or assembly drawing number, Dxxxxxx, including the revision letter, -y, to which the hardware item was built, and

nnn is the sequential serial number, 001 through 999, in the order produced.

2.3.3. Quality Assurance Provisions

Each assembly shall be produced and inspected for form, fit, dimensions and workmanship.

2.3.4. Purchaser Access

Non-escort privileges for the buyer, owner, government and owner representatives to all areas of the facilities where work is being performed shall be arranged. This will include access to all areas where material is being processed and stored. The purchaser shall have the right to witness all manufacturing processes.

2.3.5. QA Approval

LIGO QA reserves the right to inspect and approve vendor/fabricator QA plan and processes.

2.3.6. Travelers

QA travelers shall accompany all material from delivered raw stock to final components and assemblies.

2.3.7. Welding QC

A QC procedure for 100% inspection of all welded joints shall be developed and submitted for approval. This QC procedure shall be used to verify that all welds called out on the drawings have been accomplished and that the weld penetration is complete and that the weld quality is acceptable.