

ECN NO. D972119-A

INITIATOR: T. Thompson

DATE : 4-16-98

ENGINEERING CHANGE NOTICE (ECN)

NEXT ASSEMBLY NO.: D972102-1

CUSTOMER DRAWING NO.: D972120-1

DRAWING TITLE : BSC Airbearing / X-Y Translator

Mounting Plate

REVISION: FROM Orig. TO A



| <u>ITEM</u> | <u>DESCRIPTION OF CHANGE</u> (FROM... ..TO... ..) (ADD... ..) (DELETE... ..) |
|-------------|---------------------------------------------------------------------------------------|
| 1 | 1X diam. .2510 was 2X |
| 2 | Added diam. .2510 X .50 lg. Slot |
| 3 | Added 2X ½-13 UNC-2B holes to sides of plate |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| | | |
|--------------|------------------|----------------------|
| <u>TITLE</u> | <u>SIGNATURE</u> | <u>DATE APPROVED</u> |
|--------------|------------------|----------------------|

| | | |
|-------------------------|--|---------|
| CHANGED BY: Roger Smith | | 4-16-98 |
|-------------------------|--|---------|

| | | |
|--------------------------|--|---------|
| CHECKED BY: Erik Swensen | | 4-16-98 |
|--------------------------|--|---------|

| | | |
|------------------------|--|---------|
| ENGINEER: Erik Swensen | | 4-16-98 |
|------------------------|--|---------|

| | | |
|-----------------------|--|---------|
| APPROVED: T. Thompson | | 4-16-98 |
|-----------------------|--|---------|

| | | |
|---------------|-----------------------|--|
| ☐ PDF CREATED | LOCATION: D:/LIGO PDF | |
|---------------|-----------------------|--|

ECN NO. D972119-A

INITIATOR: T. Thompson

DATE : 4-16-98

PDF SENT

LOCATION:
