

DATE 7-8-98

L190-8980640-0-D

**ENGINEERING CHANGE REQUEST (ECR)**

NEXT ASSEMBLY NO. 97267

CUSTOMER DRAWING NO. 972113, d112

DRAWING TITLE F X-Transition Flange A & B

REVISION: FROM A TO B



**HYTEC**  
INCORPORATED

**DESCRIPTION OF CHANGE (Simple Notes, Identify Item if Possible):**

Ø x .406 Hole now Ø x .426 Thru  
L.594 now .614

**REASONS FOR CHANGE:**

Tempering has caused machined  
features to drift.

**IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):**

INTERFACE	RESPONSIBLE PARTY	INITIAL
<u>Line Vibrator</u>	<u>ERIC P.</u>	

NOTIFY COGNIZANT DESIGNER: Boyer

NOTIFY COGNIZANT ENGINEER: ERIC

APPROVED: Boyer