



First Results from the Mesa Beam Profile Cavity Prototype

Marco Tarallo (Universita` di Pisa)



In collaboration with J.Agresti, E.D'Ambrosio, R. DeSalvo, D.Forest(*), B.Lagrange(*), J.M. Mackowsky(*), C. Michel(*), J.L. Montorio(*), N.Morgado(*), L.Pinard(*), A.Remilleux(*), B.Simoni, P.Willems





Contents


- Environment setup: description and first tests with spherical optics
- MH mirrors: their shape and expected resonant beams
- Sample C05008: profiles analysis and simulations
- Systematic and next steps





Environment setup

- Input/output optics bench:
- Nd:YAG Mephisto laser
- Mode match telescope
- Fast photodiode for transmitted power readout
- CCD camera to control the locked TEM
- Suspended FP cavity
- Profile readout bench (CCD camera, high resolution)
- Feedback control electronics & cavity mirrors DC driving




LSC Meeting - Hanford WA, August 16th





Environment setup

Fabry-Perot cavity structure in detail







Cavity Lock Acquisition


- Tested with a R=800cm roc spherical mirror
- Two techniques:
- Side locking: control on the injection current -> easier
- Dither locking: modulation of the cavity length ->
 possibility to measure coupling with input beam but
 more sensitive to noise
- Results:
- TEM patterns characterization
- Environment capability to keep a lock




TEMs with spherical end mirrors

Resonant beams: experimental data

Hermite-Gauss TEM set



Laguerre-Gauss TEM set









TEMs with spherical end mirrors

- Qualitative analysis:
- Cylindrical symmetry gradually lost
- Difference between theoretical Hermite-Gauss and actual TEMs beam profiles (structure in the residual map)
- Marked unbalance between the two TEM10 peaks: not avoided with fine PZTs adjustments

LSC Meeting - Hanford WA,












"Mexican hat" mirrors




Numerical eigenmodes for a ideal MH Fabry-Perot interferometer:

The fundamental mode is the socalled 'Mesa Beam', wider and flatter than a gaussian power distribution











"Mexican hat" mirrors

- LMA laboratories provided three mirror samples
- C05004 (test run):
- Thin substrate (20 mm)
- large offset on the central bump
- C05008 & C05009:
- Thick substrate (30 mm)
- Both affected with a not negligible slope on the central bump




We can characterize how mirrors imperfections affects the resonant beam in such a interferometer






FFT simulations

- Using paraxial approximation, FFT codes can simulate the propagation of actual TEM patterns on optical cavities
- A Mathematica FFT routine has been dedicated to simulate our cavity beam behavior: it gave us the best tool to choose the best MH: C05008












 The slope on the central bump can be corrected applying the right mirror tilt











MH Cavity Alignment

- Spherical optics: tilt is translated in a change of the optical axis
- MH mirrors: only cylindrical symmetry
- -> resonant beam phase front change with the alignment
- Folded cavity: no preferential plane for mirrors alignment
- -> very difficult align withinOrad precision













- No stable Mesa beam profile has been acquired yet
- Higher order modes were found very easily











- FP spectrum analysis:
- TEMs identification and coupling analysis
- Non-symmetric spacing:
 as expected
- More peaks than we should see?








Other resonant TEMs:








- Misalignments and mismatching effects has been modeled to recognize "strange" resonant modes
- No way to distinguish between them












TEM00 data












- Any attempt to "drive" the beam in a centered configuration failed
- FFT: even cylindrical symmetry is definitely lost
- FP spectrum analysis: peaks are separated enough
 -> we are observing the actual cavity modes








- Coupling efficiency measurements:
- Since TEM10 seemed very stable, we investigated about the actual coupling coefficients and modes finesse
- Strange evidence: every time we tried to align the cavity, mode shapes became worse and worse (as with spherical end mirror) -> coupling measurements are not concluded yet
- Central part of the cavity seems "unstable": maybe the problem is not the MH but the other two mirrors





- Mechanical clumping, PZTs and screws stress yields deformations on the folder and input mirrors
- ~ 60 nm deformation -> three times the height of the MH central bump
- Marked astigmatism is induced
- FFT simulation with actual IM profile in progress







- Next steps:
- Change mirrors mounts (done!) and test new cavity behavior
- Model folder mirror effects on the resonant modes
- Automatic alignment, vacuum operations...
- Noise characterization: dithering possible only at low frequencies (~10 kHz) -> maybe error signal too noisy (work in progress)