## LIGO **DCN No.** E060232-00-C <u>California Institute of Technology</u> Massachusetts Institute of Technology **Document Change Notice (DCN)** Sheet 1 of 1 DOCUMENT No. TITLE (DOC-REV-GP.ID) Hanford Timing System Cable Diagram D980354-00-C CHANGE DESCRIPTION (FROM/TO): Update drawing to as-built before fiber based timing system installation.

REASON FOR CHANGE:						
ACTION: Incorporate Change	Atta	ch DCN to Drawings		Other Action (s	pecify):	
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)				DCN DISTRIBUTION		
No hardware was affected (record change only):				Barish	Coyne	Fritschel
List S/Ns which comply already:				Giaime Raab	Lazzarini Shoemaker	Lindquist Sibley
List S/Ns to be reworked/scrapped:				Sigg	Tyler	Weiss
List S/N's to be built with this change:				Whitcomb Zucker	Worden Wooley	McCarthy
				Myers	R. Abbott	, <b>,</b>
SAFETY, COST, SCHEDULE, REQUIREMENT	S IMPACT	?? NO Y	ES (If Y	ES, enter CR (C	CB) or TCP (TR	B) #)
APPROVALS:	DATE	OTHER APPROVAL	S (SPE	CIFY)		DATE
ORIGINATOR: Joshua R. Myers	10/2/06					
TASK LEADER:						
GROUP LEADER:						
DCC RELEASE:						

NEW

REV

A

DCN No.				