

ECN NO. _____

INITIATOR _____

DATE _____

ENGINEERING CHANGE NOTICE (ECN)

NEXT ASSEMBLY NO.: D972001

CUSTOMER DRAWING NO.: D972217

DRAWING TITLE: BSC Isolation Stack Leg Location & Assy Pins

REVISION: FROM A TO B



HYTEC
INCORPORATED

<u>ITEM</u>	<u>DESCRIPTION OF CHANGE</u> (FROM... ..TO... ..) (ADD... ..) (DELETE... ..)
1	Part No. in listing for dash 1, 3, &5 was D9722217, is now D972217
2	Part No. D972217-7 was D9722217-7
3	Part No. D972217-7 was D9722217-7
4	.877 was .878 on D972217-7

TITLE SIGNATURE DATE APPROVED

CHANGED BY: Roger Smith 2-11-98

CHECKED BY: _____

ENGINEER: _____

APPROVED: _____

PDF CREATED LOCATION: D:/LIGO PDF

PDF SENT LOCATION: